


p-CAT™

Pipeline Condition Assessment Technique for Water and Sewer Mains



Dr Young-il Kim
Project Director of Detection Services Pty Ltd

Water NZ 2017

pipeline condition assessment



Pipe Condition Assessment

For accessing
the remaining life
of ageing pipelines:

are a key area

when developing
a future maintenance
plan



p-CAT™


Previously, there have been little to no technologies that could assess and calculate wall thickness over long distances.

p-CAT™ fills this void as a long-distance, non-invasive scanning tool that can split pipelines into 10 meter sections with pipe wall thicknesses of 0.2 mm resolution, and provide localized faults.




p-CAT™ - Advantages and Performance

- Cost effective pipeline condition assessment method for relatively long distance pipeline section (over 2 km) with +/- 10 m spatial accuracy.
- Sub-sectional pipeline condition assessment with various resolutions from 10 m using only one set of tests both between measurement points and out of the boundary.
- Identification of pipeline anomalies (localized fault detection)
- Detects pipeline characteristics and anomalies which can be confirmed using a point sampling technique. Saving a lot of time and money.
- Various pipe diameters and materials (metallic, concrete and AC).



Fundamental Physical Mechanisms

- There is a correlation between changes in the thickness of metal and cement mortar lining forming a pipeline wall and the speed with which a wavefront from a hydraulic transient propagates along the pipeline.
- Changes in this thickness give rise to reflections which can be theoretically interpreted to obtain a distribution of damage in the pipe.
- Pipe wall damage or lining loss has a visible impact on a resultant transient pressure wave trace



Fundamental Physical Mechanisms

$$a = \sqrt{\frac{K/\rho_w}{1 + \left(\frac{K}{E_m}\right) \left(\frac{ID}{e_{eq}}\right) \psi}}$$

a = speed of propagation of hydraulic transient pressure wave

K = bulk modulus of water


ρ = density of water

E = Young's modulus of elasticity of the pipeline wall material

D = internal diameter of the pipeline



e_{eq} = wall thickness of a single material pipe
or
the total equivalent wall thickness of the composite material pipe



ψ = pipeline restraint factor.



Example Field Signals

Major Boundary Reflection, Wall Thickness/Material Change and Localized Fault





Signal Analysis

P-CAT™ analysis uses two main techniques for interpreting the results from the transient pressure wave tests:

Sub-Section Partitioned Wave Speed Analysis™

Assessment of the level of deterioration in a sub-section

Localised Fault Detection


Significant anomalies such as air pockets and blockages

What Does It Deliver?

This theory has been developed into a non-invasive technique which can determine:

- Remaining Wall Thickness including corrosion and cement mortar lining spalling
- Locations of air/gas pockets and blockages
- The sealing status of valves
- Unknown connections and branches


Testing Equipment - Generation Point



Testing Equipment - Measurement Point




Typical configuration for test series



Average Condition vs. Sub-Sectional Condition

The *p*-CAT method could identify this corroded section from within the 500 metres, allowing for targeted repair or replacement and minimising risk while saving considerable cost.




Sub-Sectional Pipeline Condition Assessment

Section Identifier	Approx. Chainage (m)		Sub-section Location on Pipeline	Approx. Length (m)	Pipe	Theoretical Wall Thickness (mm)		Remaining Effective Wall Thickness ^[1] (Difference between metal wall or cement mortar lining from the nominal theoretical value) (mm)						Sub-Sectional Average Wave Speed (m/s)
								Assumed Internal Corrosion ^[2]			Assumed External Corrosion ^[3]			
	Wall	Lining				Wall	Lining	% Remaining	Wall	Lining	% Remaining			
												Wall	Lining	
S1	0	57	AV0.2 to off-take 0	57	DN1125MSCL	8.8	20	Outside section of interest						
S2	57	421	Off-take 0 to AV1	365	OD965 MSCL	7.2	20	7.2 (0.0)	8 (-12)	85%	5.6 (-1.6)	20 (0)	83%	1048
S3	421	587	AV1 to AV2	166	OD965 MSCL	7.2	20	7.2 (0.0)	7 (-13)	83%	5.4 (-1.8)	20 (0)	81%	1040
S4	587	750	AV2 to off-take 1	162	OD965 MSCL	7.2	20	7.2 (0.0)	8 (-12)	85%	5.6 (-1.6)	20 (0)	83%	1047
S5	750	1218	Off-take 1 to off-take 2	468	OD965 MSCL	7.2	20	7.2 (0.0)	7 (-13)	84%	5.4 (-1.8)	20 (0)	81%	1042
S6	1218	1328	Off-take 2 to the horizontal section of Harper St.	110	OD965 MSCL	7.2	20	7.2 (0.0)	6 (-14)	82%	5.3 (-1.9)	20 (0)	80%	1037
S7	1328	1496	The horizontal section of Harper St to AV2.1	168	OD965 MSCL	7.2	20	Permanently entrained air and surrounding section						
S8	1496	1854	AV2.1 to SCV 3	357	OD965 MSCL	7.2	20	7.2 (0.0)	4 (-16)	80%	5.1 (-2.1)	20 (0)	78%	1030
S9	1854	2160	SCV3 to off-take 4	306	OD965 MSCL	7.2	20	7.2 (0.0)	6 (-14)	82%	5.2 (-2.0)	20 (0)	79%	1035
S10	2160	2583	Offtake 4 to possible 12 m HDPE section (444 Southport Nerang Rd)	423	OD965 MSCL	7.2	20	7.2 (0.0)	3 (-17)	79%	4.9 (-2.3)	20 (0)	76%	1023
S11	2595	2916	Possible HDPE section (442 Southport Nerang Rd) to AV4	321	OD965 MSCL	7.2	20	7.2 (0.0)	5 (-15)	81%	5.1 (-2.1)	20 (0)	78%	1032
S12	2916	3082	AV4 to Ashmore shopping centre replacement section	166	OD965 MSCL	7.2	20	7.2 (0.0)	5 (-15)	81%	5.2 (-2.0)	20 (0)	79%	1034
S13	3082	3204	Ashmore shopping centre replacement section	123	DN960 MSCL	9.6	20	9.6 (0.0)	7 (-13)	87%	7.8 (-1.8)	20 (0)	85%	1112
S14	3204	3420	Ashmore shopping centre replacement section to AV5	216	OD965 MSCL	7.2	20	7.2 (0.0)	3 (-17)	79%	4.9 (-2.3)	20 (0)	76%	1025
S15	3420	3574	AV5 to off-take 5.1	154	OD965 MSCL	7.2	20	7.2 (0.0)	6 (-14)	83%	5.3 (-1.9)	20 (0)	81%	1039
S16	3574	3887	Off-take 5.1 to SCV5	313	OD965 MSCL	7.2	20	7.2 (0.0)	7 (-13)	83%	5.4 (-1.8)	20 (0)	81%	1041
S17	3887	4138	SCV5 to AV5.1	251	OD965 MSCL	7.2	20	7.2 (0.0)	6 (-14)	82%	5.3 (-1.9)	20 (0)	80%	1037
S18	4138	4525	AV5.1 to SCV6.1	388	OD965 MSCL	7.2	20	7.2 (0.0)	7 (-13)	83%	5.4 (-1.8)	20 (0)	81%	1040

Identification of Anomalies

Identifier	Approximate location	Interpretation	Priority	Recommended action
A	OT0	Large open <u>offtake</u>	Low	None, Known system feature.
B	The horizontal section of pipe beginning on Harper St, between the intersections of Ashmore Rd and Forrest Ave. *see Section 4.3.1	Large, permanently entrained, air pocket	HIGH	Remove entrained air as it may affect system performance. There is an increased likelihood of localised internal deterioration at this point.
C	OT4 at 490 Southport Nerang Rd. *see Section 4.2	Open off-take	Medium	Exercise the valve to determine valve sealing status.
D	444 to 442 Southport Nerang Rd.	Possible HDPE replacement section or air pocket.	Medium	Check records for replacement and investigate pipeline condition.
E	Main entrance of Ashmore Shopping Centre, Southport Nerang Rd to the intersection of Southport Nerang Rd and Currumburra Rd.	Replacement section to detour around underground <u>carpark</u> constructed after original pipeline construction	Low	Update GIS maps to show difference in material.
F	AV5.1 at the intersection of Keith Turnbull Dr and <u>Dakara Dr</u> *see Section 4.3.2	Air Pocket or low wave speed material of riser	Medium	Check functionality of air valve.
G	Spanning <u>Binstead Dr</u> *see Section 4.3.3	Large, permanently entrained, air pocket near joint of Stage 1 and Stage 2 of pipeline construction.	HIGH	Remove entrained air pocket as it may affect system performance. There is an increased likelihood of localised internal deterioration at this point.
H	Intersection of <u>Bambarra St</u> and Queen St	Replacement section under new tram and road reconstruction	Low	None, Known system feature.




Anomaly: V
@ 1115 Stanley St East

Possible cause: Thicker material, repair or encasement

Nearby Feature: Open inline valve RV24375 with 2 reducers

Low priority: No action required.



Anomaly: L & M
@ Intersection of Stanley St East and Tiber St

Possible cause: Material change or possible wall thinning. Replacement MSCL section with possible deterioration and/or CI section under railway line with possible significant deterioration.

Nearby Feature: Pipeline replacement MSCL segment.

High priority: CCTV inspection and physical inspection to confirm.

Anomaly: N
@ Intersection of Stanley St East & Cavendish St


Possible cause: Branch, material change, repair or possible wall thinning

Nearby Feature: Closed offtakes RV24362 (no valve) and RV24363

Low priority: No action required.

Verification of Technique

Sections of recovers pipe



Case Study #1_ Water Main



Location	Approx. Length	Size	Material	Year
Between FPAV174 and FPAV181 (from 43M 4777/5 to 45M 3461/- as per as-constructed drawings)	2.8 km	30-inch	MSCL	1943 - 1944


Localised Fault Detection Results

Identifier	Approximate location	Interpretation	Priority	Recommended action
A	127 m south from FPAV181	Potential deterioration	Medium	Further investigation recommended
B	169 m south from FPAV181	Potential deterioration	Medium	Further investigation recommended
C	220 m south from FPAV181	Section of replacement	Low	None, known system component
D	106 m north from FPAV179	Section of replacement	Low	None, known system component
E	69 m north from FPAV177	Potential air pocket or deterioration	Medium	Further investigation recommended
F	34 m south from FPAV177	Potential deterioration	Medium	Further investigation recommended
G	116 m south from FPAV177	Potential concrete encasement for pipe section under Klinberg Road crossing	Low	Check for record of concrete encasement
H	91 m south from FPAV176	Potential presence of blockage	Medium	Further investigation recommended
I	115 m south from FPAV175	Potential concrete encasement for pipe section under Niemz Road crossing	Low	Check for record of concrete encasement

Sub-sectional Pipe Wall Condition Results

Section Identifier	Approx. Chainage (m)		Sub-section Location on Pipeline	Assumed Pipe	Approx. Length (m)	Theoretical Thickness (mm)		Remaining Total Equivalent Wall Thickness ^[1] (Difference between metal wall or cement mortar lining from the nominal theoretical value)			Sub-Sectional Average Wave Speed (m/s)
	Start	End				Wall	Lining	Wall (mm)	Lining (mm)	% remaining	
	S38	419				432	Anomaly E - potential air pocket or deterioration	30"MSCL	13	5.7	
S39	432	494	as per chainage	30"MSCL	62	5.7	12	5.7 (0.0)	5 (-7)	88%	1015
S40	494	522	From FPAV177 to 29 m south	30"MSCL	29	5.7	12	5.7 (0.0)	5 (-7)	88%	1015
S41	522	533	Anomaly F	30"MSCL	11	5.7	12	4.6 (-1.1)	0 (-12)	64%	921
S42	533	576	as per chainage	30"MSCL	42	5.7	12	5.7 (0.0)	4 (-8)	87%	1011
S43	576	610	as per chainage	30"MSCL	34	5.7	12	5.7 (0.0)	6 (-6)	89%	1019
S44	610	634	Anomaly G – concrete encasement under Klinberg Rd Crossing	30"MSCL	25						N/A ^[4]
S45	634	681	as per chainage	30"MSCL	47	5.7	12	5.6 (-0.1)	0 (-12)	77%	977
S46	681	727	as per chainage	30"MSCL	45	5.7	12	5.6 (-0.1)	0 (-12)	78%	980
S47	727	770	as per chainage	30"MSCL	43	5.7	12	5.4 (-0.3)	0 (-12)	76%	971
S48	770	816	Scour 124 to 46 m south	30"MSCL	46	5.7	12	5.6 (-0.2)	0 (-12)	78%	977
S49	816	869	as per chainage	30"MSCL	53	5.7	12	5.4 (-0.3)	0 (-12)	76%	971

Case Study #1 Water Main



Case Study #1_Water Main

- 2% of the pipeline was found to be in the most deteriorated condition with a remaining wall thickness of between 50% and 64%.
- 68% of the pipeline showed to have some deterioration with a remaining wall thickness of between 70% and 84%.
- The rest of the pipeline (29% of the total length) has remaining wall thicknesses of between 85% and 90%.






Case Study #2_Water Main

- The tests undertaken on this pipeline were conducted as part of a condition assessment project for a system in a busy CBD area. This particular section was one of two parallel pipelines following a busy main road into the city.
- The 450 CI(CL) water main was constructed from 450 CI in 1886 and later concrete lined in-situ in 1982. The pipe section of interest was 2.8 km and contains two replacement sections of 450 MSCL.



Case Study #2_ Water Main




Case Study #3_Water Main


- The pipeline of interest is the first 10 km of the 23.5 km long rising main beginning at a dam pump station. The water rising main was constructed of MSCL, with a 1085 mm outside diameter.
- For the sections with an original wall thickness of 8 mm:
 - 1.7% of the length of the pipeline was found to have the highest deterioration with remaining wall thickness of between 67% and 80%.
 - 9% of the pipeline showed to have remaining wall thickness of between 80% and 90%.
- Fourteen anomalies representing:
 - The presence of a blockage or partially closed isolation valve at an isolating valve pit at 12.11 km.
 - Four short lengths of deterioration or replacement of lower wave speed pipe material.
 - Four short lengths of deterioration, replacement of lower wave speed pipe material, or branch of a known pipe feature
 - Five potential concrete encasement sections or the presence of a blockage.



Case Study #3_ Water Main



Case Study #3_ Water Main




Case Study #4_ Water Main

The trunk water main consists of the following various pipe materials and sizes, including some sections with in-situ cement lining:

- 450 and 525 Wrought Iron (WI) constructed in 1893
- with in-situ cement lining added in 1953.
- 600, 700 and 825 Mild Steel Cement Lined (MSCL) constructed in 1979.
- 450 Cast Iron (CI), 600 WI and 600 Mild Steel Locking Bar (MSLB) constructed in 1916 with in-situ cement lining added in 1983.



Case Study #4_Water Main




Case Study #5_Sewer Rising Main


The sewer rising main was approximately 1.2 km consisting of predominantly D.N.300 AC. The pipeline section of interest lies between a pump station and an inlet of a sewerage treatment plant.



Case Study #5_Sewer Rising Main



Case Study #5_Sewer Rising Main





Case Study #6_ Sewer Rising Main

Location	Approx. Length (km)	Size (mm)	Material	Year
Pump station on Fortrose street to SCV2 located near the southern corner between number 18 and 20 Rowena st.	1.25	410 mm (as-built maps)	MS/MSCL	1976 from GIS



Case Study #6_ Sewer Rising Main



Case Study #6_ Sewer Rising Main

Key:



- AV: air valve
- Pump station
- SCV: scour valve
- TP: tapping point

Anomaly Priorities:

- High Priority
- Medium Priority
- Low Priority

Deterioration Levels:

- Level 6-7
- Level 2-3
- Level 4-5
- Level 0-1





Case Study Valve Sealing



Corroded valve



Evaluation of transient techniques undertaken at Iron Knob



2006 – 2017 Field Program

For **62** different clients

Such as water utilities, councils, contractors and mining companies

For over **176** different pipeline systems

For over **1500km** of pipeline



Thank You

Finding the
weak link...