





WATERNZ CONFERENCE Sarah Millar; Janan Nirainjanan

Öpōtiki District Council workon Private Laterals


Introducing Opotiki




Ōpōtiki and Sewer

- Sewer was old 1950's
- Leaky
- I&I resulted in > 10 x ADWF in wet weather
- High Groundwater
- Population of 3,879; median income of \$19,600
- Absentee landlords


Ōpōtiki – High Groundwater



Inflow and infiltration due to rain and high groundwater



Ōpōtiki River and Groundwater Levels & Sewage volume

















Flooding in private properties



Flooding



The Action Plan

- Tackle private laterals
- Refined over subsequent contract stages to hit easy wins obvious infiltration, illegal stormwater connections, low gully traps
- Assess and improve public sewer
- Fix leaky manholes
- Improve stormwater New trunk mains
- Additional storage basins
- More pump capacity
- Stopbanking

Funding options

- Council funding
- Property Owner funding
- Council rates funding
- Council debt funding

Rationale for council funding

- Low income home owners
- Absentee landlords to pay for work
- No direct benefit for the occupant and not experiencing any drainage difficulties

Council funding

• \$2,000,000 spread over 3 years


• Total of 1,700 properties

• 1,550 residential properties

• 150 commercial properties

Inflow and infiltration sources

Wastewater Reticulation: Inflow + Infiltration



Three contracts — Contract/Phase 1

• Phase 1 – two local contractors worked with 60 properties each

 Typical faults included pipes, faulty joints, root intrusions, broken, ineffective and low gully traps.

Illegal stormwater connection

Phase/ Contract 2

- Phase 2 One local contractor worked with 350 properties
- Loss of staff
- Delay due to weather condition
- Large portion of highly deteriorated lines

Phase/Contract 3

• Phase 3 –Tender with "Price Quality Method" for 1,200 properties


Panel contract

Dig and Repair of damaged laterals

CIPP lining of laterals



Gully trap raised





Gully trap raised



Damaged Earthenware Lateral



CIPP Lining of Laterals - Preparation



CIPP Lining of Laterals – Pumping Resin



CIPP Lining of Laterals



CIPP Lining of Laterals



Work completed to date

- Illegal stormwater connections 53 disconnected
- Low and/or damaged gully traps 404 repaired, raised or replaced
- Cracked/damaged leaking laterals 449m replaced, 698m relined
- Other sources of infiltration 202 root intrusions dug up and repaired.
- Grey water, kitchen, handbasins and other sinks removed from stormwater system.

Questions?